EDA	DECION	6	Motlanda	Protection	Section
CPA	REGION	0,	vvettanus	Protection	Section

ICIS	Chart
MINISTER STATE OF THE PARTY OF	-

## WETLANDS ENFORCEMENT FIELD INSPECTION REPORT FORM

[This form is to be completed in the field then placed into the case file. After that, no changes shall be made to these notes unless clearly noted and dated on the form. A supplemental information form should be used for additional information obtained after the field inspection]

Pre-Inspection Planning Checklist: (make su Expected weather/appropriate clothing	ure you have considered these things):  Vehicle checked, including fuel level
Check In/Out plan	Camera, GPS, shovel
Hard hat, sunglasses, gloves	Water, First Aid Kit
Date of Inspection \0 / 30 / 2017 Case/File#	EPA Inspector(s) Taul Gutierrer Statute: CWA 404 Other:
Others Present (List)	
Name Ren	presenting
Name Brandon Melville Rep	Bottonland Consulting
Jason Safford	Owner
1. TYPE OF ENFORCEMENT INSPECTION	N
(check one in each column if Compliance	Monitoring Action involved)
	Chief Special of Alice
Initial Site Visit	Compliance Monitoring Reason:
Follow-up Site Visit	Citizen complaint
ATF Permit Compliance	Core program
Enforcement Compliance	
Other	
2. SITE LOCATION / FACILITY:	MANUFACTURE WORLD TO THE PARTY OF THE PARTY
	C M 1
Case Name: (discharger/Company/site):	Juttord
7017	Choctan Rd
Address/City/County/State 506+	Choctan Rd
Library Trial. Lacks by D. Library and man	1/- 1.7.0
Brushy	State CF Zip +0+19
2020172 +	-91 767 2406
Lat.: 30,3817305	Long.: -91,2923889
(measured in field estimated in of	fice
The state of the s	
Other Location info	
Of the House !	
3. REPORTING (circle one for each item)	
Was a potential violation observed? (Y)	N
Did you inform the facility of this violation	during the inspection? (Y) N
Did the facility take any actions towards re	estoring the violation while you were there? Y N
Did you discuss general wetlands regulat	tions with a representative of the project?
Did you discuss project/site specific wetla	ands regulations with a representative of the project? N

4. DESCRIPTION OF WORK (Describe violation here, also attach sketch on page 3)												
fill in =0.5 acre for house mechanical cleaning												
Fill in =0.5 acre for house, wechenical clearing of first on vest of plot  Work in Progress? No Date work started?  Approximate Amount of Fill  5. PHOTOS: How many photos were taken? Approximate location and perspective of each photo should be noted in field sketch (page 3)												
							6. BRIEF DESCRIPTION OF WETLANDS					
							Description of Wetlands Impacted, including dominant plant species					
							BLH					
Soils Information:												
Hydrology: remnant drainge canal/ditch running down middle (old sugarcane fidd)  Description of Impacts to wetland functions (current/planned)												
Hydrology: remnant drainge Canal / at the Vunning own 8:												
Description of Impacts to wetland functions (current/planned)												
low up site vert  Fermali Complains  Constructor												
ecinal Completion (												
7. PARTY DOING WORK: Jasa Safford												
Address: 1815 Augustine St. Port Allen CA 70767												
225-25-1												
Phone: 225-505-1234												
Information Provided:												
Other responsible parties: Brandon Mehille Bottomland Consultive												
The property of the second sec												
Address: 2194 South Fieldsper Rd Duson, CA 70529												
Phone: 337-849-9978												
Information Provided:												
le Al Condess self to have been trible and to be under the self-												

	v churteen		Vertex First Factors  Vertex First Factors  Water, First Factors	abinet
Others Pro	section.			ROAD
	Foresteb	DITCH Willows along color	Hous	
ATE Porm	/ -	10/3		

Photo Log: (Note point of photo in fie Subject/Direction	File Name/number (can be added at office)
1:	
2:	
3.	
4:	
6.	
Field Notes and sketches prepared by	(sign)